

ANNUAL SURVEYS.

26035

No. 416 Survey held at London Date Feb'y March 8th 1864.
 on the Barque Soretto Master McLeod.
 Tonnage 655 Built at Rhbet When built 1859.
 By whom built Jardine Owners Gordon &
 Port belonging to Liverpool Destined Voyage -
 If Surveyed Afloat or in Dry Dock "Will head" dry dock & afloat

Last Survey, No. 25095 Port of London. Classed Y.A. 1.
62

The present Condition of the

Decks <u>in good order</u>	Treenails <u>good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Masts, <u>new</u> Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3</u> <u>"</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Rudder <u>efficient</u> <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>Yellow metal</u> When put on <u>1862</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

at this date sighted the yellow metal sheathing and found it in good condition
 condemned the masts. Gave her new fore main & mizen mast. and
 refitted the rigging. - - I am of opinion she is entitled to remain
 as class'd Y.A. 1.

Committee's Minute 18th March 1864

Character assigned 7A1

Samuel Presnall
 Certificate (if required)

No. 404 Survey held at London Date March 11th 1864.
 on the Barque Prince Alfred Master Alex^r Airth.
 Tonnage 258 Built at Aberdeen When built 1862.
 By whom built Duthie Owners J. J. Rennie.
 Port belonging to Aberdeen Destined Voyage Port Natal.
 If Surveyed Afloat or in Dry Dock "Fountain" dry dock.

Last Survey, No. 26034 Port of Aberdeen. Classed Y.A. 1.
62

The present Condition of the

Decks <u>in good order</u>	Treenails <u>good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3</u> <u>"</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Rudder <u>efficient</u> <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>Yellow metal</u> When put on <u>1862</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

at this date sighted the yellow metal and patched or repaired if
 I am of opinion she is entitled to remain
 as class'd Y.A. 1.

Committee's Minute 18th March 1864

Character assigned 9A1

Samuel Presnall
 Certificate (if required).
 Lloyd's Register
 Foundation
 LON 648-0151