

# ANNUAL SURVEYS.

26067

No. 158 on the Ship "Amrod" Master R. S. Stuart  
 Tonnage 1893 Built at Sunderland When built 1853.  
 By whom built Owners J. Allan & Co  
 Port belonging to London Destined Voyage Madras  
 If Surveyed Afloat or in Dry Dock Union Dry Dock & East India Dock

Last Survey, No. 25293 Port of London. Classed 13 A 1 63

The present Condition of the

Decks	} good where Seen	Treenails	}	Windlass and Capstan
Waterways		Breasthooks and Stemson		Pumps
Comings	} firm	Transoms, Pointers, and Crutches	} good	Boats
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.
Lower Deck Beams & Fastenings	} good where Seen	Keelsons	} and	Sails
Planksheers		Clamps and Shelves		Anchors No. of
Sheerstrakes	} Seen	Ceiling	} Sufficient	Cables
Topsides		Rudder		Hawsers and Warps
Wales	} 3	Copper Y. Moffett When put on 1863	} Standing & Running Rigging	
Plank (Bottom) and Counter				

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

Now done, the Yellow Metal Sheathing patched, head cheeks refitted and a new fore mast. She is in good and efficient condition, fit in our opinion to remain as Classed 13 A 1

Committee's Minute 5th April 1864

Character assigned 13 A 1

S. Forrester  
 Certificate (if required)

No. 120 on the Ship "Langdale" Master Browne  
 Tonnage 832 Built at Workington When built 1854  
 By whom built Owners Rathbone  
 Port belonging to Liverpool Destined Voyage Hong-Kong  
 If Surveyed Afloat or in Dry Dock Union Dry Dock

Last Survey, No. 25396 Port of London. Classed 9 A 1 63 Cont. 63. 3 pps.

The present Condition of the

Decks	} good where seen	Treenails	}	Windlass and Capstan
Waterways		Breasthooks and Stemson		Pumps
Comings	} good	Transoms, Pointers, and Crutches	} good	Boats
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.
Lower Deck Beams & Fastenings	} good where Seen	Keelsons	} Sufficient	Sails
Planksheers		Clamps and Shelves		Anchors No. of 3 B. 1 S. 2 K
Sheerstrakes	} where Seen	Ceiling	} 2	Cables
Topsides		Rudder		Hawsers and Warps
Wales	} 3	Copper Y. M. When put on	} Standing & Running Rigging	
Plank (Bottom) and Counter				

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

Now done, Starboard Hawsepipes & Naval hood renewed & 2 pintles & 1 brace with Yellow Metal - and the Metal Sheathing patched. She is in good & efficient condition, fit in my opinion to remain Classed A 1

Committee's Minute 5th April 1864

Character assigned Cont 3 A 1

S. Forrester  
 Certificate (if required)  
 Lloyd's Register  
 Foundation  
 100648-0146