

ANNUAL SURVEYS.

26077

No. 156 on the S^u Orient Survey held at London Date March 26th 18 64
 Master John Harris
 Tonnage 1133 Built at London When built 1833
 By whom built ✓ Owners Thompson & Co
 Port belonging to London Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock in Master's dock

Last Survey, No. 25483 Port of London Classed P A 1 63
 Cont 61. 3.

The present Condition of the

| | | |
|--|---|---------------------------------------|
| Decks <u>when seen Good</u> | Treenails <u>when seen Good</u> | Windlass and Capstan <u>Good</u> |
| Waterways <u>" " "</u> | Breasthooks and Stemson <u>" " "</u> | Pumps <u>" "</u> |
| Comings <u>" " "</u> | Transoms, Pointers, and Crutches <u>" " "</u> | Boats <u>" "</u> |
| Upper Deck Beams & Fastenings <u>" " "</u> | Timbers of the Frame at the Openings <u>" " "</u> | Masts, Yards, &c. <u>" "</u> |
| Lower Deck Beams & Fastenings <u>" " "</u> | Do Do at other places <u>" " "</u> | Sails <u>" "</u> |
| Planksheers <u>" " "</u> | Keelsons <u>" " "</u> | Anchors No. of <u>3 B, 1 S, 2 K</u> |
| Sheerstrakes <u>" " "</u> | Clamps and Shelves <u>" " "</u> | Cables <u>" "</u> |
| Topsides <u>" " "</u> | Ceiling <u>" " "</u> | Hawsers and Warps <u>" "</u> |
| Wales <u>" " "</u> | Rudder <u>" " "</u> | Standing & Running Rigging <u>" "</u> |
| Plank (Bottom) and Counter <u>" " "</u> | Copper <u>F & Y M</u> When put on <u>1862</u> | |
| General Observations and Opinion, | Caulking of Bottom, Deck, and Waterways <u>when seen Good</u> | |

Is now in good and efficient condition and is in my opinion fit to remain as classed

Committee's Minute 8th April 18 64
 Character assigned Cont P A 1

John Maxwell

Certificate (if required)

No. 326 on the S^u Sea Star Survey held at London Date March 29th 18 64
 Master Louitt
 Tonnage 657 Built at Aberdeen When built 1855
 By whom built ✓ Owners Louitt 2^d Liverpool
 Port belonging to Glasgow Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock in London dock

Last Survey, No. 25358 Port of London Classed 9 A 1 68
 3. 68

The present Condition of the

| | | |
|--|---|---------------------------------------|
| Decks <u>when seen Good</u> | Treenails <u>when seen Good</u> | Windlass and Capstan <u>Good</u> |
| Waterways <u>" " "</u> | Breasthooks and Stemson <u>not seen</u> | Pumps <u>" "</u> |
| Comings <u>" " "</u> | Transoms, Pointers, and Crutches <u>when seen</u> | Boats <u>" "</u> |
| Upper Deck Beams & Fastenings <u>" " "</u> | Timbers of the Frame at the Openings <u>" " "</u> | Masts, Yards, &c. <u>" "</u> |
| Lower Deck Beams & Fastenings <u>" " "</u> | Do Do at other places <u>" " "</u> | Sails <u>" "</u> |
| Planksheers <u>" " "</u> | Keelsons <u>not seen</u> | Anchors No. of <u>3 B, 1 S, 1 K</u> |
| Sheerstrakes <u>" " "</u> | Clamps and Shelves <u>when seen Good</u> | Cables <u>" "</u> |
| Topsides <u>" " "</u> | Ceiling <u>" " "</u> | Hawsers and Warps <u>" "</u> |
| Wales <u>" " "</u> | Rudder <u>" " "</u> | Standing & Running Rigging <u>" "</u> |
| Plank (Bottom) and Counter <u>" " "</u> | Copper <u>F & Y M</u> When put on <u>1863</u> | |
| General Observations and Opinion, | Caulking of Bottom, Deck, and Waterways <u>when seen Good</u> | |


Is now in good condition and is in my opinion fit to remain as classed

Committee's Minute 8th April 18 64
 Character assigned 9 A 1

John Maxwell

© 2019

Certificate (if required).



Lloyd's Register Foundation

LONG48-0185

Jan 1850
Sea Star



© 2019

Lloyd's Register
Foundation