

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 578 Survey held at London Date April 20th 18 64.
 on the Ship Anglo Saxon Master A. W. Plummer
 Tonnage 693 Built at Sunderland When built 1854.
 By whom built — Owners Frost
 Port belonging to London Destined Voyage Shanghai.
 If Surveyed Afloat or in Dry Dock "King & Queen" dry dock

Last Survey, No. 25359 Port London Classed 13. A. 1.
62

REPAIRS

At this date chiefly arising from damage by
 Grounding in Nov^r last. —

Stripped off the whole of the Yellow metal
 sheathing. Caulked the bottom down, removed some portion
 of the bearding to Rudder the same being found worm'd. — and
 repaired it. — Resheathed with Yellow metal on felt up
 to the W'ales. —

Present Condition of the

Decks <u>in good order</u>	Treenails <u>where seen good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>firm & "</u>	Timbers of the Frame at the openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>undisturb'd "</u>	Ditto Ditto at other places <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Anchors No. of <u>3</u> <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>Yellow metal</u> When put on <u>now</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good.

I am of opinion she is entitled to remain as Class'd

13. A. 1.

Samuel Pearson.

The Amount of Fee.....£ — is received by me,

Special..... 1 : 1 :

Certificate (if required) : 5 : —

Committee's Minute 26th April 18 64

Character assigned 13 A 1

record M



© 2019

Lloyd's Register
 Foundation

LON 618-0211

Anglo Saxon /



© 2019

Lloyd's Register
Foundation