

ANNUAL SURVEYS.

26147

No. 841 on the S. "Moneta" Survey held at London Date May 6th 18 64
 Tonnage 621 Built at Bristol Master Spear
 By whom built Hill Owners Spear Robinson & Co
 Port belonging to Liverpool Destined Voyage Singapore
 If Surveyed Afloat or in Dry Dock in Charter's dock

17/5/64

[Handwritten signature]

Last Survey, No. 25074 Port of London Classed 14A1
 12.62

present Condition of the

Waterways	Good	Treenails	when seen Good	Windlass and Capstan	Good
Comings	"	Breasthooks and Stemson	"	Pumps	"
Upper Deck Beams & Fastenings	"	Transoms, Pointers, and Crutches	"	Boats	"
Lower Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	"
Planksheers	"	Do Do at other places	"	Sails	"
Sheerstrakes	"	Keelsons	when seen	Anchors No. of	3B, 1S, 2K
Topsides	"	Clamps and Shelves	"	Cables	"
Wales	"	Ceiling	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Rudder	"	Standing & Running Rigging	"
General Observations and Opinion,	Caulking of Bottom, Deck, and Waterways when seen Good				

Is now in good and efficient condition and is in my opinion fit to remain as classed

[Handwritten signature: John Maxwell]

Committee's Minute 17th May 18 64
 Character assigned 14A1 *[initials]*

Certificate (if required)

No. 841 on the S. "Loeline" Survey held at London Date May 16th 18 64
 Tonnage 899 Built at Quebec Master Taylor
 By whom built 904 Owners Thompson Anderson & Co
 Port belonging to Aberdeen Destined Voyage
 If Surveyed Afloat or in Dry Dock in Clyde & Commercial docks

Last Survey, No. 18208 Port of Liverpool Classed 6A1
 3S, 60.4 gns C2 6.6

The present Condition of the	Good	Treenails	when seen Good	Windlass and Capstan	Good
Decks when seen	Good	Breasthooks and Stemson	"	Pumps	"
Waterways	"	Transoms, Pointers, and Crutches	"	Boats	"
Comings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	"
Upper Deck Beams & Fastenings	"	Do Do at other places	"	Sails	"
Lower Deck Beams & Fastenings	"	Keelsons	"	Anchors No. of	3B, 1S, 1K
Planksheers	"	Clamps and Shelves	"	Cables	"
Sheerstrakes	"	Ceiling	"	Hawsers and Warps	"
Topsides	"	Rudder	"	Standing & Running Rigging	"
Wales	"	Copper <u>E & Y M</u> When put on	1863		
Plank (Bottom) and Counter	"	Caulking of Bottom, Deck, and Waterways	Good when seen		

Is now in good and efficient condition and is in my opinion fit to carry dry cargoes and entitled to remain as classed

Committee's Minute 17th May 18 64
 Character assigned 6A1 *[initials]*

[Handwritten signature: John Maxwell]

Certificate (if required).

LON 648 - 0246