

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 117 Survey held at London Date April 27 & 28 1864
 on the "Lancashire Witch" Master Balliday
 Tonnage 283 Built at Sunderland When built 1852
 By whom built _____ Owners G. Sloan
 Port belonging to Liverpool Destined Voyage To Janeiro
 If Surveyed Afloat or in Dry Dock Gun Dry Dock

Survey, No. 17888 Port Liverpool Classed 10 A.1. 62
 Cont. 62. 3 years

Now done, the Bottom faulted and sheathed with yellow metal on felt
 Renewed on the port side, 44 rough tree stanchions of long oak
 rough tree rail G. Pine 20 ft and 35 ft of Top gallant rail

ent Condition of the

ways	good	Treenails		Windlass and Capstan	
gs		Breasthooks and Stemson		Pumps	
Deck Beams & Fastenings	firm	Transoms, Pointers, and Crutches	good	Boats	good
Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Decks	good	Ditto Ditto at other places		Sails	and
Drakes	where	Keelsons	where	Anchors No. of	
es	seen	Clamps and Shelves		Cables	Sufficient
(Bottom) and Counter	caulked	Ceiling	seen	Hawsers and Warps	
		Rudder		Standing & Running Rigging	
		Copper	G. Metal When put on now		
		Caulking of Bottom, Deck, & Waterways.	good where tested		

ral Observations and Opinion,
 She is now in good condition, fit in my opinion
 for the safe conveyance of dry and perishable
 cargoes to and from all parts of the world, and
 to remain classed A.1.

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : —

Certificate (if required) : : —

Committee's Minute 27th May 1864

Character assigned Cont 3 A 1 = second class
Charge £1.1

