

# ANNUAL SURVEYS.

*1/2 time survey.*

26179

No. 203 Survey held at Sondon Date April 18<sup>th</sup> 1864  
 on the Barge Dione Master Thos. Stephens.  
 Tonnage 289 Built at Bristol When built 1857.  
 By whom built \_\_\_\_\_ Owners Gordon Bros  
 Port belonging to Sondon Destined Voyage Algeria Bay  
 If Surveyed Afloat or in Dry Dock "King & Queen" dry dock & afloat

Received 14/6/64

Last Survey, No. 23085 Port of Sondon. Classified 13. A. 1.  
*See annexed report.*

The present Condition of the

Decks <u>in good order</u>	Treenails <u>where seen good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3</u> <u>"</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Rudder <u>efficient</u> <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>Yellow metal</u> When put on <u>1863.</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

*At this date signed the Yellow metal Sheathing. Unlucky and  
 stripped the linings off the Windlass. The main piece proved sound. Saw the  
 Nelson. Lower Hold Ceiling & Hues & Beams &c. and all appear in good condition  
 Sam of opinion she is entitled to*

Committee's Minute  
 Character assigned

7<sup>th</sup> June 1864

13 A 1

record

*remain as class'd 13. A. 1.  
 Samuel Resins.*

Certificate (if required)

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classified \_\_\_\_\_

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper _____ When put on _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18\_\_\_\_

Character assigned \_\_\_\_\_



© 2019

Lloyd's Register  
 Foundation

Certificate (if required).

L04648-0276