

REPORT of SURVEY for REPAIRS.

26/183

No. in Reg. Book. **No.** 987 Survey held at London Date May 3rd 18 64
 on the S. Monarch Master Deacon
 Tonnage 1415 Built at London When built 1844
 By whom built _____ Owners Green
 Port belonging to London Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Greens upper Dock & E. Dock

Recd. 5. 64

Last Survey, No. 25292 Port London Classed A 1 in Red
 SS. 61. 8 yds 63 2.63

REPAIRS

Seventy six planks of upper deck renewed with Dantzic Red Pine - yellow metal sheathing stripped recaulked and re-sheathed with yellow metal on Felt

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>1 1/2 x 3/4</u> When put on <u>now</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

This vessel is now in good condition fit for the conveyance of dry and perishable cargoes to and from all parts of the world and is eligible in my opinion to remain

The Amount of Fee.....£ _____ is received by me, classed A 1 in Red

Special..... 1: 1: 3

Certificate (if required) : 5: 3

Committee's Minute 10 June 18 64

Character assigned A 1 in Red

record YM



© 2019

Lloyd's Register Foundation

CON 618-10291