

# REPORT of SURVEY for REPAIRS.

26206


No. in Reg. Book. **No.** 2120 Survey held at London Date June 7<sup>th</sup> 18 64  
 on the "Look Out" Master H. Martell  
 Tonnage 139 Built at Garmouth When built 1863  
 By whom built \_\_\_\_\_ Owners B. & Co  
 Port belonging to London Destined Voyage Smyna  
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock

Last Survey, No. 2120 Port Aberdeen Classed Y A 1  
 63

## REPAIRS

The bottom caulked and sheathed to 7 feet forward and 7 1/2 feet aft with yellow metal on Felt -

Length 93.2  
 Breadth 21.4  
 Depth 12.0



## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>F &amp; M</u> When put on <u>now</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where seen tested

This vessel is eligible in my opinion to remain classed

The Amount of Fee.....£ - : 10: - is received by me, Paid

Special..... 1: 1: -

Certificate (if required) : 2: -

Committee's Minute 24<sup>th</sup> June 18 64

Character assigned Y A 1

32 91 St Helena



© 2019

Lloyd's Register Foundation

LON 648-0305