

REPORT of SURVEY for REPAIRS.

No. 26254 ~~26255~~
 Reg. No. 1 Survey held at London Date July 2nd 1864
 on the Barque "Tigri" Master Wheelan
 Tonnage 393 ~~429~~ Built at Sunderland When built 1851
 By whom built _____ Owners Smith & Co
 Port belonging to Scarborough Destined Voyage _____
 Surveyed Afloat or in Dry Dock New frame Dry Dock

Last Survey, No. 24732 Port London Classed 1 62 expired
 now done,

The Yellow Metal Sheathing patched.

Present Condition of the

Decks	} good	Treenails	} good	Windlass and Capstans	} good
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} where	Ditto at other places	} where	Sails	} sufficient
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes	} seen	Clamps and Shelves	} seen	Cables	
Top-sides		Ceiling		Hawsers and Warps	
Wales	} 3	Rudder	} 2	Standing & Running Rigging	
Plank (Bottom) and Counter		Copper <u>F & M</u> When put on <u>1861</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where seen

She is now in good condition fit in my opinion for the safe conveyance of dry and perishable cargoes and to be classed A.1.

The Amount of Fee.....£ 1 : 1 : 0 is received by me.

Special..... 1 : 1 : 0

Certificate (if required) : 5 : 0

Committee's Minute 19th July 18 64

Character assigned

Thornston & Brooke
Charge £ 1-1



© 2019

Lloyd's Register Foundation

LON 648-0346