

26256 ~~26252~~

# REPORT of SURVEY for REPAIRS.

Survey held at London Date July 17<sup>th</sup> 18 64  
the "Volante" n. Master C. Gail  
Tonnage 66 Built at Montrose When built 1862  
By whom built \_\_\_\_\_ Owners C. Birnie  
Port belonging to Montrose Destined Voyage \_\_\_\_\_  
If Surveyed Afloat or in Dry Dock Union Dry Dock

Last Survey, No. 2983 Port Dundee Classed P. A. T.  
S. 62.

REPAIRS now done:

*The vessel recaulked from keel to sheathingline, and sheathed with zinc on Paper.*

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stenson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto Ditto at other places <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Anchors No. of <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>"</u>
Trunnions <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	<u>Caulked</u> <u>Zinc on Paper</u> When put on <u>Now</u>	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>Good where seen.</u>	

*This vessel appears to be in good and efficient condition, and is eligible, in our opinion, to remain as Classed*

The Amount of Fee.....£ \_\_\_\_\_ is received by me,

Special..... £ : 10 : 6

Certificate (if required) \_\_\_\_\_

Committee's Minute 19<sup>th</sup> July 18 64

Character assigned S.F. 1  
*Record Gene*

*R. J. Reed*

*Thos. McNaughton*



© 2019  
Lloyd's Register  
Foundation  
LON 618-0348