

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 11** Survey held at London Date July 7th 18 64.
 on the B. "Balcombe" Master Bastin
 Tonnage 359 Built at Sunderland When built 1861.
 By whom built _____ Owners P. Hawkey
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock. Timehouse Dock

Last Survey, No. 25726 Port London Classed 10. A. 1.
P. 63.

REPAIRS *now done*:
 The Yellow Metal sheathing stripped, the Vessel hung in shores, recaulked from Keel to Metal line, and resheathed with Yellow Metal on Side.

Present Condition of the		
Decks <u>Good</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways "	Breasthooks and Stemson "	Pumps "
Comings "	Transoms, Pointers, and Crutches "	Boats "
Upper Deck Beams & Fastenings "	Timbers of the Frame at the openings "	Masts, Yards, &c. "
Lower Deck Beams & Fastenings "	Ditto Ditto at other places "	Sails "
Planksheers "	Keelsons "	Anchors No. of "
Sheerstrakes "	Clumps and Shelves "	Cables "
Topsides "	Ceiling "	Hawsers and Warps "
Wales "	Rudder <u>not Y.M.</u> When put on <u>Now</u>	Standing & Running Rigging "
Plank (Bottom) and Counter "	Copper <u>not Y.M.</u> When put on <u>Now</u>	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>Good where tested.</u>	

This Vessel appears to be in good and efficient Condition, and is eligible, in our opinion, to remain as Classed.

The Amount of Fee.....£ _____ is received by me,
 Special..... 1 : 1 : -
 Certificate (if required) _____
 Committee's Minute 22nd July 18 64
 Character assigned 10 A 1
second M

B. J. Reed.
Hawking
 © 2019
 Lloyd's Register
 Foundation
 LONG 618 - 0355