

ANNUAL SURVEYS.

26196
26299
Rev 11/8/64

No. 352 Survey held at London Date August 2nd 1864
on the Bk. "Alexandra" Master - J. R. Roper
Tonnage 407 Built at Sunderland When built 1862
By whom built _____ Owners Beckwith &
Port belonging to Newcastle Destined Voyage _____
If Surveyed Afloat or in Dry Dock King & Queen Dry Dock.

Last Survey, No. 7650 Port of Sunderland Classed 10 A 1.
12.62.

The present Condition of the

Decks <u>Good where seen</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame <u>at the Openings</u> _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Do Do <u>at other places</u> _____	Sails <u>Sufficient</u>
Planksheers _____	Keelsons _____	Anchors No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	<u>Copy G.M.F.</u> When put on <u>1862</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen

This Vessel appears to be in good & efficient condition; the Yellow Metal Sheathing has now been patched, & we are of opinion that she is eligible to remain as Classed.

Committee's Minute 12th August 1864

Character assigned 10 A 1

Certificate (if required)

No. 894 Survey held at London Date July 19th 1864
on the Bk. "Costa Rica" Master L. Vesente
Tonnage 299 Built at Guernsey When built 1850
By whom built _____ Owners A. Thompson
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Lavender Dry Dock.

Last Survey, No. 25793 Port of London Classed P. A. I.
Rest 63 - 5. 1. 63.

The present Condition of the

Decks <u>Good where seen</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame <u>at the Openings</u> _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Do Do <u>at other places</u> _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of <u>Sufficient</u>
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	<u>Copy G.M.F.</u> When put on <u>1863</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen

This Vessel appears to be in good & efficient condition, and is eligible, in our opinion, to remain as classed.

Committee's Minute 12th August 1864

Character assigned Rest 5 A 1

Certificate (if required).

LON 648-0388



R. J. Reed.
J. Harding

Lloyd's Register
Foundation