

REPORT of SURVEY for REPAIRS.

No. in Reg. Book: **No.** 396 Survey held at Rye Date 30th July 18 64
 on the Gawl "Pride" Master Andrew Livingstone
 Tonnage 59 Built at Sandwich When built 1857
 By whom built _____ Owners Thos^d Pordage &
 Port belonging to London Destined Voyage Baltic
 If Surveyed Afloat or in Dry Dock On the ship of Thos^d Pordage &

Key, No. 122 Port Ramsgate Classed 11A.1.

How done, Caulked throughout, her bottom sheathed with Yellow Metal on Paper. She has been thoroughly examined inside and out and found to be in good Condition - her windlass stripped, examined, and found good - the upper Pintle of the Rudder repaired.

Present Condition of the

Decks <u>Caulked</u>	Treenails _____	Windlass and Capstan _____
Waterways <u>Caulked</u>	Breasthooks and Stemson _____	Pumps _____
Comings <u>Good</u>	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame at the openings _____	Masts, Yards, &c. <u>Good and</u>
Lower Deck Beams & Fastenings _____	Ditto Ditto at other places _____	Sails <u>Sufficient</u>
Planksheers _____	Keelsons <u>Good where</u>	Anchors No. of _____
Sheerstrakes <u>Caulked</u>	Clamps and Shelves <u>seen</u>	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder <u>Yellow Metal</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter <u>Caulked</u>	Copper <u>on paper</u> When put on <u>now</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested
She is now in good Condition, fit in my opinion to remain as classed 11A.1.

J. B. Raymouth

The Amount of Fee.....£ _____ is received by me,

Special..... 2 : 2 : -

Certificate (if required) : 2 : 6

Committee's Minute 2nd September 18 64

Character assigned 11A.1

Please see expenses record N/M
£1.17.6



© 2019

Lloyd's Register Foundation

LN 648-0413