

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 149 Survey held at London Date August 18<sup>th</sup> 1864  
 on the S. "Hawich" ✱ Master - Franklin  
 Tonnage 613 Built at Hawich When built 1837  
 By whom built \_\_\_\_\_ Owners Bonus & Co.  
 Port belonging to London Destined Voyage Adelaide  
 If Surveyed Afloat or in Dry Dock Union Dry Dock.

Last Survey, No. 25686 Port London Classed G. A. T.  
H. Y. M. 62. A. 63.

REPAIRS now done: The Yellow Metal sheathing stripped, and the Vessel recaulked from keel to Metal line; part of the Topsides, & the dufts forward & aft also recaulked, and the Vessel resheathed with Yellow Metal on felt.

## Present Condition of the

Decks <u>Good where seen</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto Ditto at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of <u>Sufficient</u>
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	<u>H. Y. M.</u> When put on <u>Now</u>	

## General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested.

This Vessel appears to be in good & efficient condition, & is eligible, in our opinion, to remain as classed.

R. J. Reed

The Amount of Fee.....£ \_\_\_\_\_ is received by me,

Special..... 1 : 1 : 0

Certificate (if required) \_\_\_\_\_

Thos. M. Wain

Committee's Minute 9<sup>th</sup> September 1864

Character assigned G. B. 1  
record N.Y.M.



© 2019

Lloyd's Register Foundation

Lon 648-0422