

REPORT of SURVEY for REPAIRS.

26389

No. in Reg. Book. **No.** 817 Survey held at London Date August 1st 1864
 on the S. "Copenhagen" Master J. Thomas J. Corrie
 Tonnage 816 Built at India When built 1855
 By whom built _____ Owners J. H. Allan
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock Simetile Dry Dock

Last Survey, No. 25390 Port London Classed 13. A. 1.
P.L. & S. 62. C.M. 62. S. 12. 7. 63.

REPAIRS now done:

The Yellow Metal sheathing stripped, and the wood sheathing renailed & recaulked, and the vessel resheathed with Yellow Metal; Puntles & Braces examined & bolts retrenched; and the whole of the upper, and part of the lower, deck recaulked.

Present Condition of the

Decks <u>Good where seen</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto Ditto at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of <u>Sufficient</u>
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	<u>Y.M.</u> When put on <u>Now</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where seen

This vessel appears to be in good & efficient condition, and is eligible, in our opinion, to remain a classed.

The Amount of Fee.....£ _____ is received by me,

Special..... 1 : 1 : 0

Certificate (if required) _____

Committee's Minute

7th October 1864

Master assigned

13/11

signed

R. J. Reed

Thos. H. Wawn



© 2019

Lloyd's Register Foundation

LON 648-0457