

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 33 Survey held at London Date Feb<sup>r</sup> 21<sup>st</sup> Oct<sup>r</sup> 3<sup>rd</sup> 1864  
 on the Brig Saint Elwine Master Matthew Noall  
 Tonnage 110 Built at Bideford When built 1855  
 By whom built — Owners Jas<sup>s</sup> Young  
 Port belonging to St Ives Destined Voyage St Michaels  
 If Surveyed Afloat or in Dry Dock "Fountain" dry dock

Last Survey, No. 590 Port Penzance Classed 12. A. 1.  
~~now stand<sup>58</sup> black.~~

## REPAIRS

Now done Stripped the whole of the Yellow Metal Sheathing. Caulked the bottom, and Resheathed with yellow metal on felt up to 8 ft 6 ins. — and gave her a good overhaul.  
 — — Shipped Wendell's Main piece sound.

## Present Condition of the

Decks <u>in good order</u>	Treenails <u>good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto Ditto at other places <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Anchors No. of <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Rudder <u>effick</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>gel<sup>th</sup> Met<sup>h</sup> on felt now</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good

I am of opinion this Vessel is entitled to Reenter and Class 12. A. 1.  
 Samuel Vessons.

The Amount of Fee.....£ : : is received by me,

Special..... / : / : RG

Certificate (if required) : :

Committee's Minute 11<sup>th</sup> October 1864

Character assigned 12 A 1

account MA



© 2019

Lloyd's Register Foundation

LON 649 0002