

REPORT of SURVEY for REPAIRS.

No. in Book. **No.** 598 Survey held at London Date Feb^r 15th Oct^r 1st 1864
 on the Brig Ann Master W^m Roberts
 Tonnage 173 Built at Pwllheli When built 1840
 By whom built Prichard Owners Roberts
 Port belonging to Nevin Destined Voyage West Indies (Barbice)
 If Surveyed Afloat or in Dry Dock "Mountain" Dry dock

Last Survey, No. 1441 Port Bangor Classed Rest^d 63. Y. A. I.
 REPAIRS 8.63

Now done, overhauled the Caulking of bottom
 Caused the Deck throughout, Sheathed with
 yellow metal up to 10 ft (on felt) and overhauled
 her outside and inside.

Present Condition of the

Decks <u>in good order</u>	Treenails <u>good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>"</u>	Breasthooks and Stenson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto Ditto at other places <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Anchors No. of <u>2</u> <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>Yel^d metal on felt</u> When put on <u>now</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good

I am of opinion she is entitled to remain
 as Class'd Rest^d Y. A. I.
 Samuel Vesnoy

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 :

Certificate (if required) : 2 : 1

Committee's Minute 14th October 18 64

Character assigned Rest^d Y. A. I.
record yml



© 2019

Lloyd's Register
 Foundation

LON649-0012