

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 37 Survey held at London Date Oct^r 13th 24 1844
 on the Ship Lady Ebrington Master Ed^d Pill
 Tonnage 427 409 Built at Barnstaple When built 1852.
 By whom built — Owners J. Patchett
 Port belonging to Liverpool Destined Voyage Cape of good Hope
 If Surveyed Afloat or in Dry Dock "Billies" dry dock

Last Survey, No. 25521 Port London Classed 14. A. 1.
63

REPAIRS

Now done, stripped off the whole of the yellow metal sheathing. Hung her in Shores. Caulked from the Keel to upper part of Wales and the butts of Planking above. Renewed two lengths of deck planks. Knocked off some decayed sap from the Keelson at fore end, and resheathed with yellow metal on felt up to the height of 16ft 6.

Present Condition of the

Decks <u>in good order</u>	Treenails <u>good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto Ditto at other places <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Anchors No. of <u>3</u> <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>Yellow Metal on felt</u> When put on <u>now</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good

This Vessel being in good condition, I am of opinion is entitled to remain as Class'd 14. A. 1.

The Amount of Fee.....£ — : — : — is received by me,

Special..... 1 : 1 : —

Certificate (if required) : 5 : —

Committee's Minute 8th November 18

Character assigned 14 A 1



© 2019

Lloyd's Register Foundation

LONB49-0062