

26750

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 401 Survey held at London Date Feb 15<sup>th</sup> 1865  
on the Ship "Green Jacket" Master L. Mitchell  
Tonnage 1088 Built at St John N.B. When built 1860  
By whom built King Owners Gerrie & C. W. Kellock  
Port belonging to Liverpool Destined Voyage Aden  
If Surveyed Afloat or in Dry Dock Land Dry Dock

Last Survey, No. 25577 Port London Classed A.1.

REPAIRS Now done, the Bottom caulked and sheathed with yellow metal upon felt below the Boottopping

\* Vide Liv. Letter 12/7/67  
See P<sup>o</sup>

## Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	<u>good</u>
Comings	<u>good</u>	Transoms, Pointers, and Crutches	<u>good</u>	Boats	<u>and</u>
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	<u>where</u>	Ditto Ditto at other places	<u>where</u>	Sails	<u>sufficient</u>
Planksheers		Keelsons		Anchors No. of	<u>where</u>
Sheerstrakes	<u>seen</u>	Clamps and Shelves	<u>seen</u>	Cables	
Topsides		Ceiling	<u>3</u>	Hawsers and Warps	<u>seen</u>
Wales		Rudder		Standing & Running Rigging	<u>3</u>
Plank (Bottom) and Counter	<u>caulked</u>	Copper <u>Y Mon F</u> When put on <u>now</u>			

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where tested  
She is now in good condition and fit in our opinion to remain as classed A.1.

The Amount of Fee.....£..... is received by me,

Special..... 1 : 1 : —

Certificate (if required) .....

Committee's Minute 18<sup>th</sup> April 18 65

Character assigned 7 1/2  
Charge £ 1-1-

Hornish  
B. Waymouth