

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 19 Survey held at London Date Apr 18th to May 18th 1865
 on the "Adelaide" Master John A. Smith
 Tonnage 640 Built at Calcutta When built 1832
 By whom built Owners Merchant Shipping Coy.
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Janal Dry Dock & East India Dock

Last Survey, No. 25408 Port London Classed Red A 1 63
 SS 62 8 years

REPAIRS now done, the head knee repaired, the yellow metal stripped, the bottom caulked and resheathed with yellow metal on felt. New Bowsprit of American oak and five new yellow metal pintles to Rudder.

Present Condition of the

Decks	} good	Treenails	} good	Windlass and Capstan	} good
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	} where	Timbers of the Frame at the openings	} where	Masts, Yards, &c.	} and
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Sails	
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes	} seen	Clamps and Shelves	} seen	Cables	} sufficient
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter	caulked	Copper <u>Y.M.F.</u> When put on <u>now</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

She is now in good and efficient condition, fit in my opinion to remain as classed Red A.1.

The Amount of Fee.....£..... is received by me,

Special..... 1 : 1 : - &

Certificate (if required) : :

Committee's Minute 26th May 18 65

Character assigned

Damage Fee 2-2-
 Charge 1-1-
 record by me

Stornish



© 2019
 Lloyd's Register
 Foundation
 LON 649-0370