

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 400 Survey held at London Date May 11th 12th 1865
 on the Ship "Shannon" Master J. Daniels
 Tonnage 1292 Built at London When built 1862
 By whom built Green Owners R. & S. Green
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Green's Dry Dock

Last Survey, No. 24751 Port London Classed 13 A.1.
 63

REPAIRS

Now done, the Yellow Metal sheathing stripped off, faulked from the Keel to top of the wales and the butts above, and the middle and side work of the upper deck; and the bottom resheathed with Yellow Metal on tarred paper.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways <u>caulked</u>	Breasthooks and Stemson	Pumps
Comings <u>caulked</u>	Transoms, Pointers, and Crutches <u>good</u>	Boats <u>good</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame at the openings	Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings <u>where</u>	Ditto Ditto at other places <u>where</u>	Sails <u>and</u>
Planksheers <u>caulked</u>	Keelsons	Anchors No. of <u>sufficient</u>
Sheerstrakes <u>butts caulked</u> <u>seen</u>	Clamps and Shelves <u>seen</u>	Cables <u>where</u>
Topsides <u>do do</u>	Ceiling <u>seen</u>	Hawsers and Warps <u>seen</u>
Wales <u>caulked</u>	Rudder	Standing & Running Rigging <u>seen</u>
Plank (Bottom) and Counter <u>caulked</u>	Copper <u>YM</u> When put on <u>now</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

She is now in good and efficient condition, fit in our opinion to remain as classed 13 A.1.

The Amount of Fee.....£..... is received by me,

Special..... 1 : 1 : -

Certificate (if required)

Committee's Minute 26th May 18 65

Character assigned 13 A.1.

Charge £ 1. 1.



© 2019

Lloyd's Register Foundation

LON649-0374