

26830

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 1142 Survey held at London Date April 24th 18 65
 on the BK "Westbury" Master J. Smith
 Tonnage 329 Built at Sunderland When built 1859
 By whom built Pile Owners Walker & Co
 Port belonging to London Destined Voyage Lancaster
 If Surveyed Afloat or in Dry Dock in New frame & West India Docks

Last Survey, No. 25362 Port London Classed 10 A1
 (See annual Report.) 3-63

REPAIRS

Stripped Yellow metal sheathing, caulked from keel to metal line and re-sheathed with Yellow metal over felt.

Present Condition of the

Decks <u>when seen Good</u>	Treenails <u>when seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>" " "</u>	Breasthooks and Stemson <u>" " "</u>	Pumps <u>" "</u>
Comings <u>" " "</u>	Transoms, Pointers, and Crutches <u>" " "</u>	Boats <u>" "</u>
Upper Deck Beams & Fastenings <u>" " "</u>	Timbers of the Frame at the openings <u>" " "</u>	Masts, Yards, &c. <u>Condition, how ascertained, from enquiry & as seen from deck</u>
Lower Deck Beams & Fastenings <u>" " "</u>	Ditto Ditto at other places <u>" " "</u>	Sails <u>" "</u>
Planksheers <u>" " "</u>	Keelsons <u>" " "</u>	Anchors No. of <u>3 B, 1 S, 1 K</u>
Sheerstrakes <u>" " "</u>	Clamps and Shells <u>" " "</u>	Cables <u>" "</u>
Topsides <u>" " "</u>	Ceiling <u>" " "</u>	Hawsers and Warps <u>" "</u>
Wales <u>" " "</u>	Rudder <u>" " "</u>	Standing & Running Rigging <u>" "</u>
Plank (Bottom) and Counter <u>" " "</u>	Copper <u>F & Y M</u> When put on <u>1865</u>	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>when tested Good</u>	

Is now in good and efficient condition and is in my opinion fit to remain as classed

The Amount of Fee.....£ 1 : 1 : 0 is received by me,

Special.....

Certificate (if required)

Committee's Minute 13th June 18 65

Character assigned 10 A1



© 2019

Lloyd's Register Foundation

LON649-0385