

ANNUAL SURVEYS.

26864

✓ 112 No. 112 Survey held at London Date June 6th to July 3rd 1865.
 on the Br. + "Malay" Master Peters
 Tonnage 320 Built at Montrose When built 1862
 By whom built _____ Owners Welsh & Co.
 Port belonging to Dundee Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Globe Dock.

Last Survey, No. 3027 Port of Dundee.

Classed A. I. 1.63.

The present Condition of the

Decks Good where seen

Waterways "

Comings "

Upper Deck Beams & Fastenings "

Lower Deck Beams & Fastenings "

Planksheers "

Sheerstrakes "

Topsides "

Wales "

Plank (Bottom) and Counter "

Treenails Good where seen

Breasthooks and Stemson "

Transoms, Pointers, and Crutches "

Timbers of the Frame at the Openings "

Keelsons Do Do at other places "

Clamps and Shelves "

Ceiling "

Rudder "

Copper " When put on 1863.

Windlass and Capstan Good

Pumps "

Boats "

Masts, Yards, &c. "

Sails "

Anchors No. of Sufficient

Cables "

Hawsers and Warps "

Standing & Running Rigging "

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen.

This vessel appears to be in good and efficient condition, and eligible, in my opinion, to remain as classed - A. I.

R. J. Reed.

Committee's Minute 11th July 18 65

Character assigned 7 A 1

Certificate (if required)

524 No. 524 Survey held at London Date June 21st 18 65.

on the S. "Jubilee" Master J. Grant

Tonnage 464 Built at Workington When built 1857

By whom built _____ Owners L. Brodie

Port belonging to London Destined Voyage _____

If Surveyed Afloat or in Dry Dock Princes Dock.

Last Survey, No. 26181 Port of London.

Classed 14. A. I. 3.64.

The present Condition of the

Decks Good where seen

Waterways "

Comings "

Upper Deck Beams & Fastenings "

Lower Deck Beams & Fastenings "

Planksheers "

Sheerstrakes "

Topsides "

Wales "

Plank (Bottom) and Counter "

Treenails Good where seen

Breasthooks and Stemson "

Transoms, Pointers, and Crutches "

Timbers of the Frame at the Openings "

Keelsons Do Do at other places "

Clamps and Shelves "

Ceiling "

Rudder "

Copper W. Y. M. When put on 1864

Windlass and Capstan Good

Pumps "

Boats "

Masts, Yards, &c. "

Sails "

Anchors No. of Sufficient

Cables "

Hawsers and Warps "

Standing & Running Rigging "

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen.

The Yellow Metal Sheathing repaired. She appears to be in good and efficient condition and eligible, in my opinion, to remain as classed - 14. A. I.

R. J. Reed.

Committee's Minute 11th July 18 65

Character assigned 14 A 1

Certificate (if required)

LON649-0412