

## ANNUAL SURVEYS.

26910

No. 123 Survey held at London Date 14<sup>th</sup> July to 2<sup>nd</sup> Aug<sup>r</sup> 1865  
 on the Ship "Lansdowne" Master S. Spowart  
 Tonnage 715 Built at Sunderland When built 1856  
 By whom built \_\_\_\_\_ Owners Vickerman  
 Port belonging to London Destined Voyage Shanghai  
 If Surveyed Afloat or in Dry Dock King's Dry Dock and East India Dock

Last Survey, No. 25713 Port of London Classed 10.A.1.  
26187 64

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons Do Do at other places	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Vales	Copper <u>14 S. 16.</u> When put on <u>1864</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where seen

Now done:- Bottom sighted, - Sellow Metal patched, and  
 Corncastle-drifts caulked. She is now in good and efficient condition,  
 and fit, in my opinion, to remain as classed:- 10.A.1.

Committee's Minute 8<sup>th</sup> August 18 65

Character assigned 10.A.1

Williamson

Certificate (if required)

No. 173 Survey held at London Date 12<sup>th</sup> July to 2<sup>nd</sup> Aug<sup>r</sup> 1865  
 on the Ship "Edwin Fox" Master A. Morrison  
 Tonnage 892 Built at Calcutta When built 1853  
 By whom built \_\_\_\_\_ Owners Sellaby & Co.  
 Port belonging to London Destined Voyage Bombay  
 If Surveyed Afloat or in Dry Dock Princes Dry Dock and East India Dock

Last Survey, No. 25713 Port of London Classed 12.A.1.  
63

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons Do Do at other places	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Vales	Copper <u>14 S. 16.</u> When put on <u>1863</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

Now done:- Bottom sighted, - Sellow Metal patched and  
 painted with Peacocks and Puckaus' patent paint.  
 She is now in good and efficient condition,  
 and fit, in our opinion, to remain as classed:- 12.A.1.

Committee's Minute 8<sup>th</sup> August 18 65

Character assigned 12.A.1

Williamson  
Morrison  
 Certificate (if required).