

ANNUAL SURVEYS.

26948

No. 96 Survey held at London Date 24th to 26th July 18 65
 on the Schooner "Guiver" Master Jardinet
 Tonnage 153 Built at Forves When built 1840
 By whom built Owners J. R. Latham
 Port belonging to London Destined Voyage St. Michael
 If Surveyed Afloat or in Dry Dock Duke Shore Dry Dock

Last Survey, No. 25965 Port of London

Classed 12. A. I.
 Rest of 8 yrs.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons Do Do at other places	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>74 M</u> When put on <u>1864</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Not done: Bottom sighted; Sellar Metal patched; 37 feet of False keel renewed with American Elm; Sellar metal painted with Pencocks and Buchans' patent paint. There was a large quantity of kentledge in the hold, she was examined as far as practicable, and where seen proved to be in good and efficient condition, and is fit, in my opinion, to remain as

Committee's Minute

22nd August 1865

Classed until the end of the present year.

Character assigned

Rest. 8

87

G. Williamson
 Certificate (if required)

No. 582 Survey held at London Date 29th July to 1st Aug 18 65
 on the Ship "Bury St. Edmunds" Master J. W. Miller
 Tonnage 707 Built at Sunderland When built 1853
 By whom built Owners Blyths
 Port belonging to London Destined Voyage Mauritius
 If Surveyed Afloat or in Dry Dock Somps' Dry Dock

Last Survey, No. 24559 Port of London

Classed 13. A. I.
62

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons Do Do at other places	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>74 M</u> When put on <u>1862</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done: Bottom sighted and Sellar Metal patched. She is now in good and efficient condition, and fit, in my opinion, to remain as classed; 13. A. I.

Committee's Minute

22nd August 1865

Character assigned

13

87

G. Williamson
 Certificate (if required)