

ANNUAL SURVEYS.

27101

No. 71 Survey held at London Date 28th October 1865.
 on the Barge "Hantoon" Master John King.
 Tonnage 359 Built at New Brunswick When built 1864.
 By whom built Maynes Owners R & R. Allan.
 Port belonging to Dorset Destined Voyage Malta.
 If Surveyed Afloat or in Dry Dock Duke Shore Dock.

Last Survey, No. 2593 Port of Newport Classed 4.A.1.
 64

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Do Do at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Line</u> When put on <u>1864</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen.

Now done:- Bottom sighted and Line patched.
 She is now in good and efficient condition, and fit
 in our opinion for the safe conveyance of dry and perishable
 cargoes to and from all parts of the world, - and to remain as
 Committee's Minute 17th November 1865 Classed:- Viz. 4.A.1.
 Character assigned 4A1

Certificate (if required)

No. 574 Survey held at London Date 28th October 1865.
 on the Ship "St Robert Seppings" Master Thomas Gates.
 Tonnage 606 Built at Moulmeu When built 1844.
 By whom built 628 Owners John Allan.
 Port belonging to London Destined Voyage Madras.
 If Surveyed Afloat or in Dry Dock Union Dry Dock.

Last Survey, No. 26198 Port of London Classed 12.A.1.
 Rest 62. 8 yrs.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Do Do at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>P.V.M.</u> When put on <u>1864</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen.

Now done:- Bottom sighted and yellow metal patched.
 We examined her as far as practicable, - there being a
 quantity of Ballast and cargo in the hold, - and where seen
 she proved to be in good and efficient condition, and fit in our
 opinion to remain as classed.
 Committee's Minute 17th November 1865
 Character assigned Rest 8A1

Certificate (if required)