

ANNUAL SURVEYS.

27220

No. 212 Survey held at London Date Jan 7 23rd 1866
 on the Bk "Persia" Master J. Hudson
 Tonnage 530 Built at Scarboro' When built 1838
 By whom built _____ Owners Sindall & Co
 Port belonging to Scarboro' Destined Voyage Liversea for Leghorn
 If Surveyed Afloat or in Dry Dock Surrey Dock

Last Survey, No. 26075 Port of London Classed A.A.
64

The present Condition of the

Decks	} <u>good</u>	Treenails	} <u>good</u>	Windlass and Capstan	} <u>good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings	} <u>where</u>	Transoms, Pointers, and Crutches	} <u>where</u>	Boats	} <u>and</u>
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>seen</u>	Do Do at other places	} <u>seen</u>	Sails	} <u>efficient</u>
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes	} <u>seen</u>	Clamps and Shelves	} <u>seen</u>	Cables	} <u>3</u>
Topsides		Ceiling		Hawsers and Warps	
Wales	} <u>seen</u>	Rudder	} <u>seen</u>	Standing & Running Rigging	} <u>seen</u>
Plank (Bottom) and Counter		Copper		When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

Her upper deck fastenings, waterways, spirketting, planksheers, topsides, upper deck with its appendages, lower deck fastenings, wales, counter, plank and treenails outside to the water's edge, rudder windlass, beam, breasthook, transoms and timbers where seen are now in good condition - She is fit in my opinion for the safe conveyance of dry cargoes on short voyages and to remain as classed

Committee's Minute 30th January 1866

Character assigned A.A.

Certificate (if required)

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Do Do at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper	When put on

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18____

Character assigned _____



© 2021

Lloyd's Register
 Certificate (if required),
 Foundation

LON 650-0277