

REPORT of SURVEY for REPAIRS.

27571

No. in Reg. Book. **No.** 163 Survey held at London Date June 10th to July 5th 1866.
 on the S. "Menowen" Master Taylor
 Tonnage 129.3 Built at London When built 1860
 By whom built Green Owners Green
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Green's Upper Dock & Afloat & S. Dock.

Last Survey, No. 25902 Port London Classed 13. A. I.

REPAIRS now done as per Rule.

The whole of the Yellow Metal sheathing stripped, the vessel hung on shores, and re-caulked from keel to Metal-line, with butts of Topsides, and Resheathed with Yellow Metal on Felt.

The hold cleaned and lumbers lifted fore & aft for the examination of Keelson, which proved to be in good condition, the Wood linings stripped and the Windlass found in good condition, as also were the Hooks, Crutches, Clamps, Shelfpieces &c.

Present Condition of the

Decks <u>Good where seen</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways "	Breasthooks and Stenson "	Pumps "
Comings "	Transoms, Pointers, and Crutches "	Boats "
Upper Deck Beams & Fastenings "	Timbers of the Frame at the openings "	Masts, Yards, &c. "
Lower Deck Beams & Fastenings "	Ditto Ditto at other places "	Condition, how ascertained <u>ingins & inspection</u>
Planksheers "	Keelsons "	Sails <u>Sufficient</u>
Sheerstrakes "	Clamps and Shelves "	Anchors No. of "
Topsides "	Ceiling "	Cables "
Wales "	Rudder "	Hawsers and Warps "
Plank (Bottom) and Counter "	<u>Comp. F. Y. M.</u> When put on <u>Now</u>	Standing & Running Rigging "

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested.

She appears to be in good & efficient condition, and eligible, in our opinion, to remain classed.

13. A. I.

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : 0

Certificate (if required) : 5 : -

Committee's Minute 13th July 1866

Character assigned 13th July

record Y. M. M.

© 2019

Lloyd's Register Foundation

Low651-0036