

ANNUAL SURVEYS.

27582

No. 888 Survey held at London Date 11th June 1866
 on the Ship "Middlessex" Master S. Cammell
 Tonnage 1191 Built at Sunderland When built 1861
 By whom built _____ Owners G. Marshall
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Union Dry Dock

Last Survey, No. 26244 Port of London. Classed 13 F. 1.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good where seen</u>	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c. } <u>Good and</u>
Lower Deck Beams & Fastenings } <u>Good</u>	Ditto ditto at other places	Sails } <u>Sufficient</u>
Planksheers	Keelsons	Anchors No. of
Sheerstrakes } <u>Not Caulked</u>	Clamps and Shelves } <u>Good where</u>	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder } <u>Yellow Metal</u>	Standing & Running Rigging
Plank (Bottom) and Counter	Copper on Felt	

General Observations and Opinion. Caulking of Bottom, Deck, and Waterways Good where seen
Now done the Yellow Metal on her bottom Patched and
Painted - She is now in good and efficient Condition
fit in my opinion to remain as classed 13 F. 1.
 Committee's Minute 13th July 1866
 Character assigned 13 F. 1. M. J.

Certificate (if required)

No. 173 Survey held at London Date June 23rd 1866
 on the Ship "Marchioness of Londonderry" Master Kenney
 Tonnage 809 Built at Newcastle When built 1831
 By whom built _____ Owners G. Marshall
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Union Dry Dock

Last Survey, No. 16756 Port of London. Classed 13 F. 1.

Cont- 64 - 94

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good</u>	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c. } <u>Good and</u>
Lower Deck Beams & Fastenings } <u>Good</u>	Ditto ditto at other places	Sails } <u>Sufficient</u>
Planksheers	Keelsons	Anchors No. of
Sheerstrakes } <u>Buttly</u>	Clamps and Shelves } <u>Good where</u>	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder } <u>Yellow Metal</u>	Standing & Running Rigging
Plank (Bottom) and Counter	Copper on Felt	

General Observations and Opinion. Caulking of Bottom, Deck, and Waterways Good where seen
Now done her Yellow Metal Sheathing Patched and
Painted - She is now fit in my opinion to remain as
classed 13 F. 1.
 Committee's Minute 13th July 1866
 Character assigned Cont 9 F. 1. M. J.

Certificate (if required)

LON 651 - 0045