

ANNUAL SURVEYS.

27639

Recd 4.7.66

No. 821 Survey held at London Date July 5th 1866
 on the Ship "Mermaid" Master H. Rose
 Tonnage 1321 Built at St John When built 1853
 By whom built Wilson & Co Owners Wilson & Co
 Port belonging to Liverpool Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Wigram's Dry Dock and East India Dock

Last Survey, No. 26959 Port of London Classed 4 A.1
Sept. 63 5 yrs.

The present Condition of the

Decks	} <u>good</u>	Treenails	} <u>good</u>	Windlass and Capstan	} <u>good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats <u>5</u>	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c. <u>and</u>	
Lower Deck Beams & Fastenings	} <u>where</u>	Ditto ditto at other places	} <u>where</u>	Sails	} <u>efficient</u>
Planksheers		Keelsons		Anchors No. of <u>3 B. 1 S. 2 H.</u>	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales	} <u>seen</u>	Rudder	} <u>seen</u>	Standing & Running Rigging	} <u>seen</u>
Plank (Bottom) and Counter		Copper <u>T & Y M</u> When put on <u>1865</u>			

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where seen
Now done, the bottom sighted; she is in good and efficient condition fit in my opinion to remain as classed A.1.

Committee's Minute 10th August 1866
 Character assigned Rest 5 1/2 mit
Stornish
 Certificate (if required)

No. 150 Survey held at London Date July 7th 11th 1866
 on the "The Lord Warden" Master H. Green
 Tonnage 1237 Built at Sunderland When built 1862
 By whom built Green Owners H. Green
 Port belonging to London Destined Voyage Green's Dry Dock & East India Dock
 If Surveyed Afloat or in Dry Dock Green's Dry Dock & East India Dock

Last Survey, No. 27061 Port of London Classed 13 A.1
65

The present Condition of the

Decks	} <u>good</u>	Treenails	} <u>good</u>	Windlass and Capstan	} <u>good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c. <u>and</u>	
Lower Deck Beams & Fastenings	} <u>where</u>	Ditto ditto at other places	} <u>where</u>	Sails	} <u>efficient</u>
Planksheers		Keelsons		Anchors No. of <u>3 B. 1 S. 2 H.</u>	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales	} <u>seen</u>	Rudder	} <u>seen</u>	Standing & Running Rigging	} <u>seen</u>
Plank (Bottom) and Counter		Copper <u>T & Y M</u> When put on <u>1865</u>			

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where seen
Now done, the bottom sighted, a fore and after hood on each side renewed with English Oak; she is now in good and efficient condition fit in my opinion to remain as classed 13 A.1.

Committee's Minute 10th August 1866
 Character assigned 13 1/2 mit
Stornish
 Certificate (if required)