

REPORT of SURVEY for REPAIRS.

27700

No. in Reg. Book. **No.** 5 Survey held at London Date April 23rd to May 10th 1866
 on the "Macchaute" Master Taylor
 Tonnage 717 Built at Switzerland When built 1856
 By whom built Laird Owners Beazley
 Port belonging to Liverpool Destined Voyage Canal Dock & East India Dock
 If Surveyed Afloat or in Dry Dock Canal Dock & East India Dock

Last Survey, No. 4721 Port Greenock Classed 13. A. I.
10. 63.

REPAIRS now done:

The Yellow Metal sheathing stripped, and the vessel re-caulked from keel to metal-line and re-sheathed with Yellow Metal over felt.

Present Condition of the

Decks <u>Good where seen</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto Ditto at other places <u>"</u>	Condition, how ascertained? <u>by examination & weighing</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>Sufficient</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Wales <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>W. & M.</u> When put on <u>now</u>	Standing & Running Rigging <u>"</u>

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested.

This vessel appears to be in good and efficient condition and eligible, in our opinion, to remain classed 13. A. I.

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : 0 Paid at Liverpool

Certificate (if required) : : :

Committee's Minute 11th September 1866

Character assigned 13 A I

record



© 2019

Lloyd's Register Foundation

LOU 651 - 0139