

27742

REPORT of SURVEY for REPAIRS.

No. in Reg. Book, **No.** 11 Survey held at London Date Sept 19th 18 66
on the "Canadian" Master Russell
Tonnage 705 Built at Greenock When built 1857
By whom built W Orr Owners W Orr
Port belonging to Greenock Destined Voyage Hong Kong
If Surveyed Afloat or in Dry Dock in Union & East India Decks

Last Survey, No. 25292 Port London Classed 11A1
63

REPAIRS

Stripped Yellow metal sheathing caulked keel to Planksheer with Waterway seams and port deck and re-sheathed with Yellow metal over felt.

Present Condition of the

Decks <u>where seen Good</u>	Treenails <u>where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>" " "</u>	Breasthooks and Stemson <u>" " "</u>	Pumps <u>"</u>
Comings <u>" " "</u>	Transoms, Pointers, and Crutches <u>" " "</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>" " "</u>	Timbers of the Frame at the openings <u>" " "</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>" " "</u>	Ditto Ditto at other places <u>" " "</u>	Condition, how ascertained <u>from inquiry & seen from deck</u>
Planksheers <u>" " "</u>	Keelsons <u>" " "</u>	Sails <u>"</u>
Sheerstrakes <u>" " "</u>	Clamps and Shelves <u>" " "</u>	Anchors No. of <u>3 B. 1 S. 1 K.</u>
Topsides <u>" " "</u>	Ceiling <u>" " "</u>	Cables <u>"</u>
Wales <u>" " "</u>	Rudder <u>" " "</u>	Hawsers and Warps <u>"</u>
Plank (Bottom) and Counter <u>" " "</u>	Copper <u>ASYM</u> When put on <u>1866</u>	Standing & Running Rigging <u>"</u>
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>where seen Good</u>	

Is now in good and efficient condition and is in my opinion fit to remain as classed.

The Amount of Fee.....£ : : is received by me, Wm Maxwell

Special.....

Certificate (if required),

Committee's Minute 25th September 1866

Character assigned 11A1



© 2019

Lloyd's Register Foundation

LDN 651-071

Linnadi



© 2019

Lloyd's Register
Foundation