

REPORT of SURVEY for REPAIRS.

27775

No. in Reg. Book. **No.** 514 Survey held at London Date September 26 to 29 18 66.
 on the BR + "Christine" Master G. Purdy
 Tonnage 306 Built at Southwick When built 1863 - 9 mo
 By whom built _____ Owners Haukey & Co
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock Nelson Dock

Last Survey, No. 27536 Port London Classed 11. A. I.
6. 66.

REPAIRS now done:

The yellow metal sheathing stripped, the vessel re-caulked from keel to metal-line, and re-sheathed with yellow metal over felt.

Present Condition of the

Decks <u>Good where seen</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways //	Breasthooks and Stemson //	Pumps //
Comings //	Transoms, Pointers, and Crutches //	Boats //
Upper Deck Beams & Fastenings //	Timbers of the Frame at the openings //	Masts, Yards, &c. //
Lower Deck Beams & Fastenings //	Ditto Ditto at other places //	Condition, how ascertained <u>by inquiry & inspection</u>
Planksheers //	Keelsons //	Sails <u>Sufficient</u>
Sheerstrakes //	Clamps and Shelves //	Anchors No. of //
Topsides //	Ceiling //	Cables //
Wales //	Rudder <u>F.V.M.</u> When put on <u>now</u>	Hawsers and Warps //
Plank (Bottom) and Counter //	Caulking of Bottom, Deck, & Waterways. <u>Good where tested.</u>	Standing & Running Rigging //

General Observations and Opinion,

She appears to be in good and efficient condition, and eligible, in our opinion, to remain classed 11. A. I.

P. J. Reed.

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : 0

Certificate (if required) : :

Committee's Minute 5th October 1866

Character assigned 11 A I
record 9 M



© 2019

Lloyd's Register Foundation

LON G51-0195