

27782

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 162 Survey held at London Date Augth 20th Septth 13th 18 66
on the BK "Westmoreland" Master Gashung
Tonnage 452 Built at Sunderland When built 1850
By whom built _____ Owners Anderson, Thompson & Co
Port belonging to London Destined Voyage West Indies
If Surveyed Afloat or in Dry Dock Nelson Slipway
Last Survey, No. 26944 Port London Classed 13. A. T.
7. 65.

REPAIRS

Now done:

The yellow metal sheathing shipped, the vessel re-caulked from keel to Waterway seam, and re-sheathed with yellow metal over felt.

The midship bulwarks now renewed.

Present Condition of the

Decks	Treenails	Windlass and Capstan
<u>Good where seen</u>	<u>Good where seen</u>	<u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>by inquiry & inspection</u>
Planksheers	Keelsons	Sails <u>Sufficient</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	<u>F. Y. M.</u> When put on <u>now</u>	Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested

She appears to be in good and efficient condition, and eligible, in my opinion, to remain as classed.

R. J. Reed.

The Amount of Fee.....£..... is received by me,

Special..... 1 : 1 : 0

Certificate (if required) :

Committee's Minute 9th October 18 66

Character assigned 13

record Y. M. W. H.



© 2019

Lloyd's Register Foundation

LN 651-0201