

# REPORT of SURVEY for REPAIRS.

27870

No. in Reg. Book. **No.** 61 Survey held at London Date 1<sup>st</sup> Nov 18 66  
 on the "James Holmes" Master A. Poulson  
 Tonnage 304 Built at Sunderland When built 1853  
 By whom built \_\_\_\_\_ Owners Nelson & Co  
 Port belonging to London Destined Voyage West Indies  
 If Surveyed Afloat or in Dry Dock New Crane dock & N<sup>o</sup> Dock

Last Survey, No. 1188 Port Southampton Classed 11 A.1  
 64

## REPAIRS

Wales doubled with 2½ inch American Rock Elm over Felt, (6 strakes) the two lower fastened with through and dump bolts of yellow metal, and the remainder with Galvanized Iron. The yellow metal stripped off, recaulked from keel to black-strakes and the yellow metal sheathing renewed on Felt.

### Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings <u>Good</u>	Ditto Ditto at other places <u>Good</u>	Condition, how ascertained <u>Good &amp; Sufficient</u>
Planksheers	Keelsons	Sails
Sheerstrakes <u>where seen</u>	Clamps and Shelves <u>where seen</u>	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>1 1/2 M</u> When put on <u>now</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good where tested</u>	

This vessel is now in good condition and is eligible in my opinion to remain as classed

The Amount of Fee.....£ 1 : : is received by me,

Special..... 1 : : :

Certificate (if required) : : :

Committee's Minute 9<sup>th</sup> November 18 66

Character assigned A.1

Record Repair

A.1  
Thos. M. Wawn  
P. Reed.



Lloyd's Register  
 Foundation

LON 651 - 0 275