

ANNUAL SURVEYS.

27878

881 No. 101 Survey held at London Date November 10th 18 66
 on the M. + "Constantia" Master Mason
 Tonnage 464 Built at Sunderland When built 1854
 By whom built _____ Owners Parker & Co.
 Port belonging to Sunderland Destined Voyage Demarara
 If Surveyed Afloat or in Dry Dock Nelson Dry Dock.

Last Survey, No. 8053 Port of Sunderland. Classed 10. A. 1.
 3.64.

The present Condition of the

Decks <u>Good where seen</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the Openings <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Ditto ditto at other places <u>do</u>	Sails <u>Sufficient do</u>
Planksheers <u>do</u>	Keelsons <u>do</u>	Anchors No. of <u>do</u>
Sheerstrakes <u>do</u>	Clamps and Shelves <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Ceiling <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>	Copper <u>Y. M. & F.</u> When put on <u>1864</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen
The yellow metal sheathing patched. she appears to be in good and efficient condition, and eligible, in my opinion, to remain classed.

A. J. Reed.

Committee's Minute 13th November 18 66

Character assigned 10 A 1 MA

Certificate (if required)

No. _____ Survey held at _____ Date _____ 18 ____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18 ____

Character assigned _____



© 2019

Lloyd's Register

Certificate (if required)

LOW 651 - 0283