

ANNUAL SURVEYS.

27904

No. 149 Survey held at London Date Nov^r 24th 18 66
 on the "Harwich" Master Hutchings
 Tonnage 613 Built at Harwich When built 1857
 By whom built _____ Owners Bonus & Co
 Port belonging to London Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock in Union & London Docks

Rev-26-11-66

Last Survey, No. 26351 Port of London Classed GA1
8.64

The present Condition of the

Decks <u>when seen Good</u>	Treenails <u>when seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of <u>3 B, 1 S, 2 K</u>
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper <u>F.Y.M.</u> When put on <u>1864</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways when seen Good

Is now in good and efficient condition and is in my opinion
 fit to remain as classed

Committee's Minute 27th November 1866

Character assigned

GA1

N.B.D.

I was informed that it was not intended to re-class this
 this vessel until her return from her present voyage when her
 metal would be stripped J.M. Certificate (if required)

John Matwell

No. _____ Survey held at _____ Date _____ 18 _____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper _____ When put on _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18 _____

Character assigned _____



© 2019

Lloyd's Register
 Foundation

Certificate (if required).

LOW 651-0304

Charmelo



© 2019

Lloyd's Register
Foundation