

27973

# REPORT of SURVEY for REPAIRS.

Nov 11. 11. 64

No. in Reg. Book. **No.** \_\_\_\_\_ Survey held at London Date 5<sup>th</sup> Oct. to 19<sup>th</sup> Oct. 1864  
 on the Ship "Norfolk" Master Carson  
 Tonnage 953 Built at London When built 1857  
 By whom built \_\_\_\_\_ Owners Migiam &  
 Port belonging to London Destined Voyage Melbourne  
 If Surveyed Afloat or in Dry Dock Migiam's dry dock and East India Dock's

Last Survey, No. 25595 Port London. Classed AT 13 Years

## REPAIRS

*(Now done)* Her bottom sighted and the yellow metal sheath patched, fore and main channels raised about 12 inches, also the chain and preventer plates taken off, lengthened and refitted.  
 Her windlass lifted, stripped and found good and the fore and main rigging overhauled and refitted.

### Present Condition of the

Decks <u>good where seen</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stenson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto Ditto at other places <u>"</u>	Sails <u>and</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Anchors No. of _____
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables _____
Topsides <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps _____
Wales <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Sufficient</u>
Plank (Bottom) and Counter <u>"</u>	<sup>ym</sup> Copper on Felt When put on <u>1863</u>	

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where seen

*This vessel is now in good condition and is eligible in my opinion to remain as Classed AT*

The Amount of Fee.....£ : : is received by me,  
 Special...../ : / :  
 Certificate (if required) : :

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_

Character assigned \_\_\_\_\_

