

Half time Survey REPORT of SURVEY for REPAIRS.

27974

No. in Reg. Book. **No.** 241 Survey held at London Date Decr to 18th 18 66.
 on the B^{te} "Peterborough" Master B Orchard
 Tonnage 560 Built at Sunderland When built 1859 (8 mo.)
 By whom built Austin Owners Hantkey
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Nelson dry Dock, and West India Docks.

Last Survey, No. 26668 Port London Classed B.A.1 (2.65.)
 REPAIRS Now done.

The timbers lifted all fore and aft; peaks cleared; floor examined, and found good; also the windlass stripped, main piece examined which proved good; the caulking of topsides tested and found efficient.

The bottom sighted and yellow metal patched.

Present Condition of the

Decks	} <u>good and firm</u>	Treenails	}	Windlass and Capstan	<u>stripped</u>	} <u>Good and Sufficient</u> <u>where seen</u>
Waterways		Breasthooks and Stemson		Pumps	<u>four</u>	
Comings	Transoms, Pointers, and Crutches	<u>Good</u>	Boats	<u>four</u>		
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings		Masts, Yards, &c.	<u>good</u>		
Lower Deck Beams & Fastenings	Ditto Ditto at other places	<u>where</u>	Condition, how ascertained	<u>inspⁿ and enquiry</u>		
Planksheers	Keelsons	<u>good</u>	Sails			
Sheerstrakes	Clamps and Shelves	<u>seen</u>	Anchors	No. of <u>3 B.W. 1/1</u>		
Topsides	Ceiling		Cables			
Wales	Rudder	<u>good</u>	Hawsers and Warps			
Plank (Bottom) and Counter	Copper	<u>and Y.M. When put on 1865.</u>	Standing & Running Rigging			
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.			<u>Good where tested</u>		

She is now in good and efficient condition and fit in my opinion to remain as Classed, viz B.A.1.

Joseph Allen.

The Amount of Fee.....£..... is received by me.

Special.....1-1-0

Certificate (if required)

Committee's Minute 28th December 1866

Character assigned B.A.1



© 2019

Lloyd's Register Foundation

LN651-0362