

## ANNUAL SURVEYS.

27988

No. 72 Survey held at London Date Dec<sup>r</sup> 31<sup>st</sup> 18 66  
 on the S<sup>d</sup> "Maid of Orleans" Master Smith  
 Tonnage 897 Built at United States When built 1848  
 By whom built Owners D. Barr  
 Port belonging to Ardrossan Destined Voyage Kurrachee  
 If Surveyed Afloat or in Dry Dock in Ratcliff Cross & East India Docks

Last Survey, No. 2156 Port of Glasgow.

Classed A1 in Red  
S.S. 64 5 ps. 2.64.

The present Condition of the

Decks	where seen Good	Treenails	where seen Good	Windlass and Capstan	Good
Waterways	" " "	Breasthooks and Stemson	" " "	Pumps	"
Comings	" " "	Transoms, Pointers, and Crutches	" " "	Boats	"
Upper Deck Beams & Fastenings	" " "	Timbers of the Frame	" " "	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	" " "	Keelsons	" " "	Sails	"
Planksheers	" " "	Clamps and Shelves	" " "	Anchors	No. of 3 B, 1 S, 1 K
Sheerstrakes	" " "	Ceiling	" " "	Cables	"
Topsides	" " "	Rudder	" " "	Hawsers and Warps	"
Wales	" " "	Copper	When put on	Standing & Running Rigging	"
Plank (Bottom) and Counter	" " "				

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways where seen Good

Renewed windlass of English Oak  
 Is now in good and efficient condition fit for the safe conveyance of dry & perishable cargoes to and from all parts of the world & is in my opinion fit to remain as classed.

Committee's Minute 4<sup>th</sup> January 1867

Character assigned

A1 red

M.S.

John Maxwell

Certificate (if required)

No. 142 Survey held at London Date Dec<sup>r</sup> 31<sup>st</sup> 18 66  
 on the S<sup>d</sup> "George Rainy" Master John Tickers  
 Tonnage 519 Built at Liverpool When built 1861  
 By whom built Clarke Owners Sandbach  
 Port belonging to Liverpool Destined Voyage Demarara  
 If Surveyed Afloat or in Dry Dock in Bridge & West India Docks

Last Survey, No. 19223 Port of Liverpool.

Classed 10 A1  
2.65

The present Condition of the

Decks	where seen Good	Treenails	where seen Good	Windlass and Capstan	Good
Waterways	" " "	Breasthooks and Stemson	" " "	Pumps	"
Comings	" " "	Transoms, Pointers, and Crutches	" " "	Boats	"
Upper Deck Beams & Fastenings	" " "	Timbers of the Frame	" " "	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	" " "	Keelsons	" " "	Sails	"
Planksheers	" " "	Clamps and Shelves	" " "	Anchors	No. of 1 B, 1 S, 2 K
Sheerstrakes	" " "	Ceiling	" " "	Cables	"
Topsides	" " "	Rudder	" " "	Hawsers and Warps	"
Wales	" " "	Copper	F.T.M. When put on 1865	Standing & Running Rigging	"
Plank (Bottom) and Counter	" " "				

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways where seen Good

Is now in good and efficient condition and in my opinion fit to remain as classed.

Committee's Minute 4<sup>th</sup> January 1867

Character assigned

10 A1

M.S.

John Maxwell

Certificate (if required).

Lloyd's Register  
Foundation

LOU 651-0342



Mr. Orleans

date

Geo. R. R. R.

date



© 2019

Lloyd's Register  
Foundation