

28108

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 575 Survey held at London Date Feb 28th 18 67  
on the Solent Master Nixon  
Tonnage 732 Built at Lowes When built 1854  
By whom built White Owners J. Shepherd  
Port belonging to London Destined Voyage Hong Kong  
If Surveyed Afloat or in Dry Dock in Limekiln & West India Docks

Last Survey, No. 26670 Port London Classed 13 A1  
1.65

## REPAIRS

Stripped Yellow metal sheathing, caulked from keel to metal line and re-sheathed with Yellow metal over felt.

### Present Condition of the

Decks <u>Where seen Good</u>	Treenails <u>Where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>" " "</u>	Breasthooks and Stemson <u>" " "</u>	Pumps <u>"</u>
Comings <u>" " "</u>	Transoms, Pointers, and Crutches <u>" " "</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>" " "</u>	Timbers of the Frame at the openings <u>" " "</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>" " "</u>	Ditto Ditto at other places <u>" " "</u>	Condition, how ascertained <u>from enquiry &amp; seen from deck</u>
Planksheers <u>" " "</u>	Keelsons <u>" " "</u>	Sails <u>"</u>
Sheerstrakes <u>" " "</u>	Clamps and Shelves <u>" " "</u>	Anchors No. of <u>3 B 1 S, 2 K</u>
Topsides <u>" " "</u>	Ceiling <u>" " "</u>	Cables <u>"</u>
Wales <u>" " "</u>	Rudder <u>" " "</u>	Hawsers and Warps <u>"</u>
Plank (Bottom) and Counter <u>" " "</u>	Copper <u>F.Y.M.</u> When put on <u>1864</u>	Standing & Running Rigging <u>"</u>
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>When tested Good</u>	

Is now in good and efficient condition and in my opinion eligible to remain as classed.

The Amount of Fee.....£ : : is received by me, John Maxwell  
Special..... 1 : 1 : 0  
Certificate (if required) : : }

Committee's Minute 5<sup>th</sup> March 18 67

Character assigned 13 A1 record MM

