

28160

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 118 Survey held at London Date March 13th 18 67
on the 8 " Invincible Master Beeching
Tonnage 657 Built at Workington When built 1857
By whom built Tell Owners Bushby & Co
Port belonging to Workington Destined Voyage China
If Surveyed Afloat or in Dry Dock in Limekiln & London Docks.

Last Survey, No. 19097 Port Liverpool Classed 13 A1
11. 64

REPAIRS

Stripped Yellow metal sheathing; caulked from keel to metal line and re-sheathed with Yellow metal over paper.

Present Condition of the

Decks <u>where seen Good</u>	Treenails <u>where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>" " "</u>	Breasthooks and Stemson <u>" " "</u>	Pumps <u>" " "</u>
Comings <u>" " "</u>	Transoms, Pointers, and Crutches <u>" " "</u>	Boats <u>" " "</u>
Upper Deck Beams & Fastenings <u>" " "</u>	Timbers of the Frame at the openings <u>" " "</u>	Masts, Yards, &c. <u>" " "</u>
Lower Deck Beams & Fastenings <u>" " "</u>	Ditto Ditto at other places <u>" " "</u>	Condition, how ascertained <u>from enquiry & as seen from deck</u>
Planksheers <u>" " "</u>	Keelsons <u>" " "</u>	Sails <u>" " "</u>
Sheerstrakes <u>" " "</u>	Clamps and Shelves <u>" " "</u>	Anchors No. of <u>3 B, 1 S, 2 K</u>
Topsides <u>" " "</u>	Ceiling <u>" " "</u>	Cables <u>" " "</u>
Wales <u>" " "</u>	Rudder <u>" " "</u>	Hawsers and Warps <u>" " "</u>
Plank (Bottom) and Counter <u>" " "</u>	Copper <u>YM</u> ^{paper} When put on <u>1867</u>	Standing & Running Rigging <u>" " "</u>
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>where tested Good</u>	

Is now in good and efficient condition and in my opinion eligible to remain as classed.

The Amount of Fee.....£ — : — : is received by me, John Maxwell

Special..... 1 : 1 : 0 { SP

Certificate (if required) : 5 : {

Committee's Minute 29th March 18 67

Character assigned 13 A1

record



© 2019

Lloyd's Register Foundation

LOW 651-D 509

Immable
date



© 2019

Lloyd's Register
Foundation