

REPORT of SURVEY for REPAIRS.

28207

No. in Reg. Book. **No.** 23 Survey held at London Date April 13th 18 64
 on the S. York Master Breary
 Tonnage 865 Built at Sunderland When built 1854
 By whom built 940 Owners J. H. Allan
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock in Limekiln & East India Docks

Last Survey, No. 26682 Port London Classed 13 A1
2.65

REPAIRS

c.f

Doubled yellow metal sheathing with about 1550 sheets of yellow metal from keel upwards.

Present Condition of the

Decks <u>where seen Good</u>	Treenails <u>where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways " " "	Breasthooks and Stemson " " "	Pumps " "
Comings " " "	Transoms, Pointers, and Crutches " " "	Boats " "
Upper Deck Beams & Fastenings " " "	Timbers of the Frame at the openings " " "	Masts, Yards, &c. " "
Lower Deck Beams & Fastenings " " "	Ditto Ditto at other places " " "	Condition, how ascertained <u>from enquiry & as seen from deck</u>
Planksheers " " "	Keelsons " " "	Sails " "
Sheerstrakes " " "	Clamps and Shelves " " "	Anchors No. of <u>3 B, 1 S, 1 K</u>
Topsides " " "	Ceiling " " "	Cables " "
Wales " " "	Rudder " " "	Hawsers and Warps " "
Plank (Bottom) and Counter " " "	Copper <u>F.Y.M.</u> When put on <u>1865</u>	Standing & Running Rigging " "

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. where seen Good

Is now in good and efficient condition and in my opinion eligible to remain as classed.

The Amount of Fee.....£ — : — : — is received by me.

Special..... — : — :

Certificate (if required) : :

Committee's Minute 18th April 18 64

Character assigned 13 A1 M.A.S.



© 2019

Lloyd's Register Foundation

LONG51-0543

York
mural



© 2019

Lloyd's Register
Foundation