

28209

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 466 Survey held at London Date 6th to 16th March 1864
on the Barge "Sheviot" Master J. H. Henderson
Tonnage 501 Built at Shields When built 1882 (7. Mo.)
By whom built Smith Owners J and W. Smith
Port belonging to Newcastle Destined Voyage Madras
If Surveyed Afloat or in Dry Dock Green's Upper dock and East India Dock.

Last Survey, No. 26724 Port London Classed 14. A. 1.
11/64.

REPAIRS

Now done:- The Yellow metal sheathing stripped off the Bottom and caulked from keel to the metal line. Resheathed the Bottom with Yellow metal on brown paper.

The Timbers lifted and the Peaks cleared:- the Floors, Stelson, Stemson and Sternson examined and found good.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps <u>Two</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>Four</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>By inquiry & observation</u>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 B. 1 S. 2 K.</u>
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>When put on</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.	

She is now in good and efficient condition, and fit, in my opinion, to remain classed: A. 1.

J. Williamson.

The Amount of Fee.....£ : : is received by me,
Special..... 2 : 2 :
Certificate (if required) : :

Committee's Minute 18th April 18 64

Character assigned 14 B.

record G. M. W. S.



© 2019

Lloyd's Register Foundation

LD 651-0 546