

28216

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 53 Survey held at London Date 27th Mar. to 1st April 1867
on the Barge "Lady Head" Master John James
Tonnage 457 Built at Southwick When built 1885 (3. No.)
By whom built Mills Owners Hudson's Bay Company
Port belonging to London Destined Voyage Hudson's Bay
If Surveyed Afloat or in Dry Dock Messrs Hignams' Dock and West India Dock

Last Survey, No. 27435 Port London Classed 13 A 1
5.66

REPAIRS

Now done: Examined the Bottom, and caulked the vessel from the Keel to the upper edge of the Doubling.
Painted the Bottom with patent Paint. Main
Topgallant-yard new of Spruce.

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways	} <u>Good</u>	Breasthooks and Stemson	} <u>Good</u>	Pumps <u>Two</u>	} <u>Good where seen.</u>
Comings		Transoms, Pointers, and Crutches		Boats <u>3 No.</u>	
Upper Deck Beams & Fastenings	} <u>where</u>	Timbers of the Frame at the openings	} <u>where</u>	Masts, Yards, &c.	} <u>Condition, how ascertained by inquiry & observation.</u>
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Sails	
Planksheers	} <u>seen.</u>	Keelsons	} <u>seen.</u>	Anchors No. of <u>3 B. 15. 3 K.</u>	} <u>Good and sufficient</u>
Sheerstrakes		Clamps and Shelves		Cables	
Topsides	} <u>seen.</u>	Ceiling	} <u>where seen.</u>	Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter	<u>Caulked</u>	Copper Paint When put on <u>Now</u>			
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>Good where tested.</u>				

She is in good and efficient condition, and fit, in my opinion, to remain classed. A 1

The Amount of Fee.....£ : : is received by me,

Special..... / : / :

Certificate (if required) : : :

Committee's Minute 23rd April 1867 by

Character assigned 13 A 1 QMS.



© 2019

Lloyd's Register
Foundation

CON 651-0553