

Half time Survey

REPORT of SURVEY for REPAIRS.

28264

No. in Reg. Book. **No.** 779 Survey held at London Date Feb 22nd to 4th March 1867
 on the B^k "Annie Braginton" Master E. J. Bolt
 Tonnage 413 Built at Shields When built 1860 (1 mo.)
 By whom built Metcalf Owners Braginton R. D. Turcan
 Port belonging to London Destined Voyage By Austin Bros
 If Surveyed Afloat or in Dry Dock Kincardine Fore and Aft dry Dock. ✓ per Bill of Sale produced 25.5.67

Last Survey, No. 7915 Port Newcastle Classed B. A. 1 (3.60)
 REPAIRS Now done.

Sighted bottom, the yellow metal stripped, peaks cleared, and timbers lifted all fore and aft, floors and keelsons &c, examined and found good; the Windlass stripped, main piece found good; Caulked from keel to the plank sheers, and resheathed the bottom with yellow metal on felt

Present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good</u>	Windlass and Capstan	} <u>Good and sufficient where seen</u>
Waterways		Breasthooks and Stemson		Pumps <u>Two</u>	
Comings		Transoms, Pointers, and Crutches		Boats <u>Three</u>	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c. <u>good</u>	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained <u>inspⁿ and engineering</u>	
Plank sheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of <u>3 B 1/2 S. 2 H</u>	
Topsides		Ceiling		Cables	
Wales	Rudder <u>Had good</u>	Hawsers and Warps	} <u>Good</u>		
Plank (Bottom) and Counter	Copper <u>on</u> When put on <u>nom</u>	Standing & Running Rigging			
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways. <u>Good where tested</u>			

She is now in good and efficient condition and fit in our opinion to remain as Classed For. A. 1.
Joseph Keen.

The Amount of Fee.....£ 1 : 0 : 0 is received by me,
 Special.....2 . 2 . 0
 Certificate (if required) : 5 :

Committee's Minute 14th May 1867
 Character assigned 13/2 record W.S.