

28303

ANNUAL SURVEYS.

No. _____ Survey held at London Date May 23rd 1867
 on the Ship "Carnegieen" Master R Phillips
 Tonnage 225 Built at Aberdeen When built 1867 (4 mo)
 By whom built Humphrey Owners Gonnou and
 Port belonging to Aberdeen Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock King and Queen dry Dock

No. 24 of 1867

Last Survey, No. 2339 Port of Aberdeen Classed G.A.1 (4.6%)

The present Condition of the		
Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>F and Y.M.</u> When put on <u>1867</u>	Good where seen.
General Observations and Opinion,	Caulking of Bottom, Deck, and Waterways	

Sighted bottom; she is now in good and efficient condition and fit in our opinion to remain as classed.

Committee's Minute 28th May 1867 by Joseph Keew.
 Character assigned G.A.1 M.S. Thos. McNaughton
 Certificate (if required)

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____		
The present Condition of the		
Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper _____ When put on _____	
General Observations and Opinion,	Caulking of Bottom, Deck, and Waterways	

Committee's Minute _____ 18____
 Character assigned _____