

# REPORT of SURVEY for REPAIRS.

28450

No. in Reg. Book. **No.** 1061 1076 Survey held at London Date July 3<sup>rd</sup> to 10<sup>th</sup> 1867.  
 on the Ship "Mount Stuart Elphinstone" Master J. A. Freebody  
 Tonnage 611 Built at Bombay When built 1826  
 By whom built \_\_\_\_\_ Owners Marchant & Co. Comp<sup>y</sup> (Lim<sup>d</sup>)  
 Port belonging to London Destined Voyage fixed  
 If Surveyed Afloat or in Dry Dock Canal dry Dock and West India D<sup>ocks</sup>  
 Last Survey, No. 19381 Port Liverpool Classed Red. A. 1  
SS 60 - 8 ins 65  
 REPAIRS None done.

Renewed forward one Shift of rider Keelson with Sautsue Oak; fitted a few graving pieces in the ceiling of the Hold; sighted bottom and patched the Yellow Metal, and payed it with Peacocks patent paint.

## Present Condition of the

### Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

General Observations and Opinion,

### Treenails

Breasthooks and Stenson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons greater part seen

Clamps and Shells

Ceiling part seen

Rudder Had good

Copper and Y.M. When put on 1865.

Caulking of Bottom, Deck, & Waterways. Good where seen

### Windlass and Capstan

Pumps 2

Boats 3

Masts, Yards, &c. good

Condition, how ascertained insp<sup>n</sup> and enquiry Sufficient

Sails

Anchors No. of 3 B. 15. 18. where

Cables

Hawsers and Warps

Standing & Running Rigging

She is now in good and efficient condition, being "fit for the safe conveyance of dry and perishable goods to and from all parts of the World," also fit in my opinion to remain classed A. 1. in Red.

The Amount of Fee.....£ — : — : is received by me

Special..... 1 : 1 : — gd

Certificate (if required) : :

Committee's Minute 23<sup>rd</sup> July 18 67

Character assigned Unleaded



© 2021

Lloyd's Register  
Foundation 0182