

ANNUAL SURVEYS.

28196

No. 415 Survey held at London Date June 8 to Aug 9 1867
 on the Ship "Shannon" Master Watson
 Tonnage 1292 Built at London When built 1862
 By whom built Green Owners R & S Green
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Green's Dry Dock & East India Dock

Last Survey, No. 27583 Port of London Classed 13 A. 1
 66

The present Condition of the

| | | |
|--|--|---------------------------------|
| Decks | Treenails | Windlass and Capstan |
| Waterways <u>caulked</u> <u>good</u> | Breasthooks and Stemson <u>good</u> | Pumps <u>good</u> |
| Comings | Transoms, Pointers, and Crutches | Boats |
| Upper Deck Beams & Fastenings | Timbers of the Frame at the Openings | Masts, Yards, &c. |
| Lower Deck Beams & Fastenings <u>where</u> | Do Do at other places <u>where</u> | Sails <u>where</u> |
| Planksheers | Keelsons | Anchors No. of <u>3 B 15.2K</u> |
| Sheerstrakes | Clamps and Shelves | Cables |
| Topsides <u>seen</u> | Ceiling | Hawsers and Warps <u>seen</u> |
| Wales | Rudder | Standing & Running Rigging |
| Plank (Bottom) and Counter | Copper <u>YM</u> When put on <u>1865</u> | |

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

Now done, The bottom sighted and the Yellow Metal patched and painted below the light water mark - the bulks of topsides caulked and the seams overhauled - the upper deck waterways, plank sheer and covering board caulked and the caulking of the deck overhauled. Two Kedge Anchors now supplied - She is now in good condition fit in my opinion to remain as Committee's Minute 13th August 1867

Character assigned 13 A. 1 M.S.

Classed 13 A. 1

Certificate (if required)

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

| | | |
|-------------------------------|--------------------------------------|----------------------------|
| Decks | Treenails | Windlass and Capstan |
| Waterways | Breasthooks and Stemson | Pumps |
| Comings | Transoms, Pointers, and Crutches | Boats |
| Upper Deck Beams & Fastenings | Timbers of the Frame at the Openings | Masts, Yards, &c. |
| Lower Deck Beams & Fastenings | Do Do at other places | Sails |
| Planksheers | Keelsons | Anchors No. of |
| Sheerstrakes | Clamps and Shelves | Cables |
| Topsides | Ceiling | Hawsers and Warps |
| Wales | Rudder | Standing & Running Rigging |
| Plank (Bottom) and Counter | Copper _____ When put on _____ | |

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute _____ 18____

Character assigned _____



© 2021

Lloyd's Register

Foundation

LON652-0218